

From glowbugs@theporch.com Sat Jul 13 22:07:13 1996
Return-Path: glowbugs@theporch.com
Received: from uro (localhost.theporch.com [127.0.0.1]) by uro.theporch.com
(8.7.5/AUX-3.1.1) with SMTP id WAA20093; Sat, 13 Jul 1996 22:04:21 -0500 (CDT)
Date: Sat, 13 Jul 1996 22:04:21 -0500 (CDT)
Message-Id: <199607140304.WAA20093@uro.theporch.com>
Errors-To: ws4s@midtenn.net
Reply-To: glowbugs@theporch.com
Originator: glowbugs@theporch.com
Sender: glowbugs@theporch.com
Precedence: bulk
From: glowbugs@theporch.com
To: Multiple recipients of list <glowbugs@theporch.com>
Subject: GLOWBUGS digest 235
X-Listprocessor-Version: 6.0c -- ListProcessor by Anastasios Kotsikonas
X-Comment: Please send list server requests to listproc@theporch.com
Status: 0

GLOWBUGS Digest 235

Topics covered in this issue include:

- 1) Re: Building info
by Kevin Pease <hamradio@mm1001.theporch.com>
- 2)
by Kim Herron <kherron@voyager.net>
- 3) Matching Hallicrafters paint
by k7yha@juno.com (richard h. arland)
- 4) Hallicrafters Collectors
by k7yha@juno.com (richard h. arland)

Date: Fri, 12 Jul 1996 22:01:08 -0500 (CDT)
From: Kevin Pease <hamradio@mm1001.theporch.com>
To: michael silva <mjsilva@ix.netcom.com>
Subject: Re: Building info
Message-ID: <Pine.LNX.3.91.960712215914.25130B-1000000@mm1001.theporch.com>

Most Sweep Tubes are rated I belive for CCS service since the sweep circuit is continuous duty and TV'S are run for many hours. Maybe 75 watts input is reasonabel and at 75% eficienacy which is possible 50-50 watts could be had.

Kevin Pease
WB0JZG Mount Juliet, TN.

Date: Sat, 13 Jul 1996 21:51:37 -0400 (EDT)
From: Kim Herron <kherron@voyager.net>
To: Boatanchors@theporch.com
Cc: Glowbugs@theporch.com
Message-ID: <199607140151.VAA25802@vixa.voyager.net>

Hi Gang,

I have need of a good front panel for a Hammarlund HQ-170. I am willing to buy a whole unit or just a front panel if anyone has one (Charlie and Robert, your phone is ringing). If any one knows where one can be had or if you have one, please let me know here or you may call me at 1-616-677-3706. If I'm not here leave a message and I'll call you back. If I am here, I'll be happy to call you back on my nickel (read lots of money to ATT). Thanks ever so much!!

KIM
kherron@voyager.net

Date: Sun, 14 Jul 1996 02:30:23 PST
From: k7yha@juno.com (richard h. arland)
To: glowbugs@theporch.com
Subject: Matching Hallicrafters paint
Message-ID: <19960714.023032.4543.7.k7yha@juno.com>

Hi Gang:
I'm back after a loooooong time off of internet.

I purchased a Hallicrafters SX-130/HT-40 combo at a hamfest last weekend. The previous owner tried painting it a non-standard gray to spiff it to sell it at the flea market.

I posted this on the QRP-L listing and received one reply about using Krylon #1606 pewter gray.

My next question is: How does one get paint off of the rubber feet that are rivited to the cabinet? It seems that the rocket scientist who painted my rigs neglected to mask off the rubber feet. Any ideas?

73 rich K7YHA

Date: Sun, 14 Jul 1996 02:35:48 PST
From: k7yha@juno.com (richard h. arland)
To: glowbugs@theporch.com
Subject: Hallicrafters Collectors
Message-ID: <19960714.023555.4543.9.k7yha@juno.com>

Does anyone know of a list or newsgroup that caters to just Hallicrafters collectors? I realize that this list is for tube-type QRP gear (NOTE: I have taken the 6DQ6 out of the HT-40 and am running it from the driver...so it is a QRP rig).

Recently Boatanchors informed me, when I tried to subscribe, that they wanted money to share in the costs of maintaining the list. This is kind of a turn-off since my only interests in tube gear revolves around collecting (for use, not to sit on shelves) Hallicrafters gear and restoring Zenith Transoceanic radios.

73 rich K7YHA

End of GLOWBUGS Digest 235
